

F.L.MATTOCK BUILDING  
60 South Main Street  
Eureka Springs  
Carroll County  
Arkansas

HABS NO.AR-33

HABS  
ARK  
8-EURSP  
1-

PHOTOGRAPHS  
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY  
NATIONAL PARK SERVICE  
Department of the Interior  
Southeast Region  
Atlanta, Georgia 30303

STATE ARKANSAS	COUNTY CARROLL	TOWN OR VICINITY EUREKA SPRINGS
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) "F. L. MATTOCK BLDG." (Carved into limestone structure)		HABS NO. AR-33
SECONDARY OR COMMON NAMES OF STRUCTURE "WEAVER BUILDING" (Floyd Weaver--occupant from mid-60's to late 1983)		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 60 South Main Street, Eureka Springs, Arkansas 72632		
DATE OF CONSTRUCTION (INCLUDE SOURCE) "1917" (Carved into structure)	ARCHITECT(S) (INCLUDE SOURCE) UNKNOWN	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) built as a Ford Agency garage & has been used for no other purpose than an auto repair garage. Due to common & minimum-standard mat'ls used, along with its simple & unimaginative design, the structure makes no architectural statement. Location was unaccommodative to downtown appearance--past or present. Historically, it was uneventful. (Other garages were also in existence)		
STYLE (IF APPROPRIATE) N/A		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Constructed of scrap stone with red clay brick fascia; plate glass windows, concrete slab on grade (no foundation); rolled roofing (wood) on plywood roof deck.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) "Shell" building -- 40' x 80', approximately 16' high		
EXTERIOR FEATURES OF NOTE 6" double walls		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Vacant--no interior furnishings		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES No known alterations or additions made--the lack of which contributed to its decay.		
PRESENT CONDITION AND USE Front eaves have fallen off. Broken and/or patched trusses, with sagging roof. 6" out of plumb from floor to ceiling. Floor slab uneven and cracked, with sunken areas of up to 4". (See photos encl.)		
OTHER INFORMATION AS APPROPRIATE Vacated and unused since late 1983. Condemned in July, 1984 as a safety hazard.		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Eureka Springs Museum (no information found) Eureka Springs Public Library (no information found) Eureka Springs Times Echo (no information found)		
COMPILER, AFFILIATION Charles Fargo, Transit Director, City of Eureka Springs		DATE 8-1-85